
Concrete patch repair required to promenade







Current promenade condition with temporary repair

Promenade condition prior to temp patch repair.

Replacement of joint sealant required on wave-return wall



Concrete patch repair required to seawall







Replacement of joint sealant required on promenade




Concrete patch repair required on promenade



Concrete repair required to blockwork seawall



Replacement of joint sealant required on wave-return wall



Concrete repair (re-casting) required to beach access step



Concrete repair required to blockwork seawall



Replacement of mortar joint required on blockwork seawall



Concrete patch repair required to slipway




Cutting flat of pointed timber groyne element required



Cutting flat of pointed timber groyne element required



Additional fixings required to secure timber groyne element



Additional fixings required to secure timber groyne element

