


Promenade before concrete patch repair



Promenade after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Promenade before concrete patch repair



Promenade after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples


Beach access step before concrete repair



Beach access step after concrete repair




Beach access step after concrete repair



Beach access step before concrete repair



Blockwork seawall before concrete patch repair




Blockwork seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples


Timber groyne before H&S removal of tops of stakes with pointed ends



Timber groyne after H&S removal of tops of stakes with pointed ends




Blockwork seawall before concrete patch repair



Blockwork seawall after concrete patch repair



Blockwork seawall before concrete patch repair




Blockwork seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Promenade before concrete patch repair




Promenade after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples


Promenade before concrete patch repair




Promenade after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples



Promenade before concrete patch repair




Promenade after concrete patch repair




Hunstanton Coastal Defence: 2023-24 financial year repair examples

Promenade before concrete patch repair




Promenade after concrete patch repair





Hunstanton Coastal Defence: 2023-24 financial year repair examples



Slipway before concrete patch repair




Slipway after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Slipway before concrete patch repair




Slipway after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Slipway before concrete patch repair




Slipway after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Slipway before concrete patch repair



Slipway after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Slipway before concrete patch repair




Slipway after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Steps before concrete patch repair




Steps after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Seawall before concrete patch repair



Seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Seawall before concrete patch repair



Seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Seawall before concrete patch repair



Seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples

Seawall before concrete patch repair



Seawall after concrete patch repair



Hunstanton Coastal Defence: 2023-24 financial year repair examples



Seawall before concrete patch repair



Seawall after concrete patch repair